

April 26, 2019

Joseph Coviello
Acting Executive Director
Jersey City Municipal Utilities Authority
555 Route 440
Jersey City, NJ 07305

Subject: Annual Update Regarding Utilities on the Ciasulli Property

540 Route 440, Jersey City, New Jersey

Dear Mr. Coviello:

Honeywell is providing this annual notice update regarding site conditions and activities at the Ciasulli Property (Site) as part of its focus on preventing any subsurface work from disturbing the environmental remedies implemented at the site, and in accordance with Paragraph 81 of the Consent Decree Regarding Sites 79 and 153 South (Ciasulli Consent Decree).

Under the Ciasulli Consent Decree, Honeywell must provide an annual update notice regarding site conditions and activities related to the utilities in the area of the Ciasulli Property. The previous notices were provided by Honeywell in a letter dated April 27, 2018. No remediation activities have occurred at the Site since our last notice. Site information is provided below.

Honeywell completed remediation of chromium-impacted soil at the Ciasulli Property during 2010. The remedial actions, approved by the New Jersey Department of Environmental Protection (NJDEP), included in situ treatment in one part of the Site and limited excavation in another area.

Information on the property is provided below. Honeywell has also implemented remedial actions at the former Morris Canal. These actions are described in notice letters pertaining to the Morris Canal and New Jersey City University.

The Ciasulli Property

The Ciasulli Property, operating as Metro Honda, is an automobile dealership that encompasses approximately 3 acres along Route 440 between Carbon Place and Fisk Street in Jersey City, New Jersey (see attached aerial location map). The property consists of two parcels: the main car dealership facility and a separate vehicle parking, located east of the main facility. Various utility lines are located on the Site. A remedial investigation showed that soils present on portions of the Site contained hexavalent chromium above New Jersey's most stringent residential soil guideline of 20 milligrams/kilogram.

Pursuant to the NJDEP approved remedial plan, in 2010 Honeywell Honeywell implemented a remedial action involving excavation of a small portion of the Site along the sidewalk area near the corner of Fisk Street and Mortorano

April 26, 2019 Joseph Coviello, Jersey City Municipal Utilities Authority Utilities on Study Area 5 Site 079 - Ciasulli Property Page 2 of 2

Way, and treatment of soils via in-situ injection of a reductant in the western part of the Site, between the car dealership building and Route 440. That area is covered with asphalt paving that prevents exposure to contaminants which may remain in soils.

The owner of the Ciasulli property has placed a deed restriction on the Site that requires Honeywell to maintain these remedial measures. Honeywell is committed to maintaining the integrity of the asphalt cap in compliance with New Jersey law and its obligations under the Ciasulli Consent Decree. Honeywell submitted a Remedial Action Report to the NJDEP during September 2011, which was approved by the NJDEP in February 2012. The NJDEP issued a Restricted Use No Further Action Letter and Remedial Action Permit for soils in May 2012. In 2014, post-remediation sampling was performed and results were included in a Post-Treatment Sampling Results Report submitted in February 2015 and approved by the NJDEP in December 2015. Based on the remedial actions completed and post-treatment sampling results, no further post-remediation soil or groundwater sampling is anticipated and post-remediation cap inspections and reporting will continue under the existing Deed Notice, Remedial Action Soil Permit, and Long-Term Monitoring Plan.

If you are planning to conduct any work on or near the subject property (as shown on attached map), we request that you notify Honeywell at least 10 business days in advance or as soon as the work is known. You can report any such pending work by calling 855-727-2658, a special number Honeywell has obtained in order to receive such notifications.

As always, we appreciate your cooperation. If you have any questions or would like additional information, please feel free to call me at 973-455-3302.

Sincerely,

Maria Kaouris

Remediation Manager

Maria Karris

Attachment: Aerial Location Map

MK:jh/sqf

cc: (electronic copy)

Michael Daneker – Arnold & Porter LLP Jeremy Karpatkin – Arnold & Porter LLP

John Morris – Honeywell

Resa Drasin - Woehling and Freeman

Robert Woehling - Woehling and Freeman

Joseph Clifford – Wood Environment & Infrastructure Solutions, Inc.



April 26, 2019

Christopher Tomlin North Region Maintenance Manager Jersey Department of Transportation 200 Stierli Court Mt. Arlington, NJ 07856

Subject: Annual Update Regarding Utilities on the Ciasulli Property

540 Route 440, Jersey City, New Jersey

Dear Mr. Tomlin:

Honeywell is providing this annual notice update regarding site conditions and activities at the Ciasulli Property (Site) as part of its focus on preventing any subsurface work from disturbing the environmental remedies implemented at the site, and in accordance with Paragraph 81 of the Consent Decree Regarding Sites 79 and 153 South (Ciasulli Consent Decree).

Under the Ciasulli Consent Decree, Honeywell must provide an annual update notice regarding site conditions and activities related to the utilities in the area of the Ciasulli Property. The previous notices were provided by Honeywell in a letter dated April 27, 2018. No remediation activities have occurred at the Site since our last notice. Site information is provided below.

Honeywell completed remediation of chromium-impacted soil at the Ciasulli Property during 2010. The remedial actions, approved by the New Jersey Department of Environmental Protection (NJDEP), included in situ treatment in one part of the Site and limited excavation in another area.

Information on the property is provided below. Honeywell has also implemented remedial actions at the former Morris Canal. These actions are described in notice letters pertaining to the Morris Canal and New Jersey City University.

The Ciasulli Property

The Ciasulli Property, operating as Metro Honda, is an automobile dealership that encompasses approximately 3 acres along Route 440 between Carbon Place and Fisk Street in Jersey City, New Jersey (see attached aerial location map). The property consists of two parcels: the main car dealership facility and a separate vehicle parking lot, located east of the main facility. Various utility lines are located on the Site. A remedial investigation showed that soils present on portions of the Site contained hexavalent chromium above New Jersey's most stringent residential soil guideline of 20 milligrams/kilogram.

April 26, 2019 Christopher Tomlin, Jersey Department of Transportation Utilities on Study Area 5 Site 079 - Ciasulli Property Page 2 of 2

dealership building and Route 440. That area is covered with asphalt paving that prevents exposure to contaminants which may remain in soils.

The owner of the Ciasulli property has placed a deed restriction on the Site that requires Honeywell to maintain these remedial measures. Honeywell is committed to maintaining the integrity of the asphalt cap in compliance with New Jersey law and its obligations under the Ciasulli Consent Decree. Honeywell submitted a Remedial Action Report to the NJDEP during September 2011, which was approved by the NJDEP in February 2012. The NJDEP issued a Restricted Use No Further Action Letter and Remedial Action Permit for soils in May 2012. In 2014, post-remediation sampling was performed and results were included in a Post-Treatment Sampling Results Report submitted in February 2015 and approved by the NJDEP in December 2015. Based on the remedial actions completed and post-treatment sampling results, no further post-remediation soil or groundwater sampling is anticipated and post-remediation cap inspections and reporting will continue under the existing Deed Notice, Remedial Action Soil Permit, and Long-Term Monitoring Plan.

If you are planning to conduct any work on or near the subject property (as shown on attached map), we request that you notify Honeywell at least 10 business days in advance or as soon as the work is known. You can report any such pending work by calling 855-727-2658, a special number Honeywell has obtained in order to receive such notifications.

As always, we appreciate your cooperation. If you have any questions or would like additional information, please feel free to call me at 973-455-3302.

Sincerely,

Maria Karris

Maria Kaouris
Remediation Manager

Attachment: Aerial Location Map

MK:jh/sgf

cc: (electronic copy)

Michael Daneker – Arnold & Porter LLP Jeremy Karpatkin – Arnold & Porter LLP

John Morris – Honeywell

Resa Drasin – Woehling and Freeman

Robert Woehling - Woehling and Freeman

Joseph Clifford - Wood Environment & Infrastructure Solutions, Inc.



April 26, 2019

Public Service Electric and Gas Company P.O. Box 1023 Cranford, NJ 07016

Subject: Annual Update Regarding Utilities on the Ciasulli Property

540 Route 440, Jersey City, New Jersey

To Whom It May Concern:

Honeywell is providing this annual notice update regarding site conditions and activities at the Ciasulli Property (Site) as part of its focus on preventing any subsurface work from disturbing the environmental remedies implemented at the site, and in accordance with Paragraph 81 of the Consent Decree Regarding Sites 79 and 153 South (Ciasulli Consent Decree).

Under the Ciasulli Consent Decree, Honeywell must provide an annual update notice regarding site conditions and activities related to the utilities in the area of the Ciasulli Property. The previous notices were provided by Honeywell in a letter dated April 27, 2018. No remediation activities have occurred at the Site since our last notice. Site information is provided below.

Honeywell completed remediation of chromium-impacted soil at the Ciasulli Property during 2010. The remedial actions, approved by the New Jersey Department of Environmental Protection (NJDEP), included in situ treatment in one part of the Site and limited excavation in another area.

Information on the property is provided below. Honeywell has also implemented remedial actions at the former Morris Canal. These actions are described in notice letters pertaining to the Morris Canal and New Jersey City University.

The Ciasulli Property

The Ciasulli Property, operating as Metro Honda, is an automobile dealership that encompasses approximately 3 acres along Route 440 between Carbon Place and Fisk Street in Jersey City, New Jersey (see attached aerial location map). The property consists of two parcels: the main car dealership facility and a separate vehicle parking lot, located east of the main facility. Various utility lines are located on the Site. A remedial investigation showed that soils present on portions of the Site contained hexavalent chromium above New Jersey's most stringent residential soil guideline of 20 milligrams/kilogram.

April 26, 2019 Public Service Electric and Gas Company Utilities on Study Area 5 Site 079 - Ciasulli Property Page 2 of 2

dealership building and Route 440. That area is covered with asphalt paving that prevents exposure to contaminants which may remain in soils.

The owner of the Ciasulli property has placed a deed restriction on the Site that requires Honeywell to maintain these remedial measures. Honeywell is committed to maintaining the integrity of the asphalt cap in compliance with New Jersey law and its obligations under the Ciasulli Consent Decree. Honeywell submitted a Remedial Action Report to the NJDEP during September 2011, which was approved by the NJDEP in February 2012. The NJDEP issued a Restricted Use No Further Action Letter and Remedial Action Permit for soils in May 2012. In 2014, post-remediation sampling was performed and results were included in a Post-Treatment Sampling Results Report submitted in February 2015 and approved by the NJDEP in December 2015. Based on the remedial actions completed and post-treatment sampling results, no further post-remediation soil or groundwater sampling is anticipated and post-remediation cap inspections and reporting will continue under the existing Deed Notice, Remedial Action Soil Permit, and Long-Term Monitoring Plan.

If you are planning to conduct any work on or near the subject property (as shown on attached map), we request that you notify Honeywell at least 10 business days in advance or as soon as the work is known. You can report any such pending work by calling 855-727-2658, a special number Honeywell has obtained in order to receive such notifications.

As always, we appreciate your cooperation. If you have any questions or would like additional information, please feel free to call me at 973-455-3302.

Sincerely,

Maria Karris

Maria Kaouris Remediation Manager

Attachment: Aerial Location Map

MK:jh/sgf

cc: (electronic copy)

Michael Daneker – Arnold & Porter LLP
Jeremy Karpatkin – Arnold & Porter LLP
John Morris – Honeywell
Resa Drasin – Woehling and Freeman
Robert Woehling – Woehling and Freeman

Joseph Clifford – Wood Environment & Infrastructure Solutions, Inc.



April 26, 2019

Bob Hass Engineering/Construction Leader PSE&G Transmission 4000 Hadley Road, MC 429 South Plainfield, NJ 07080

Subject: Annual Update Regarding Utilities on the Ciasulli Property

540 Route 440, Jersey City, New Jersey

Dear Mr. Hass:

Honeywell is providing this annual notice update regarding site conditions and activities at the Ciasulli Property (Site) as part of its focus on preventing any subsurface work from disturbing the environmental remedies implemented at the site, and in accordance with Paragraph 81 of the Consent Decree Regarding Sites 79 and 153 South (Ciasulli Consent Decree).

Under the Ciasulli Consent Decree, Honeywell must provide an annual update notice regarding site conditions and activities related to the utilities in the area of the Ciasulli Property. The previous notices were provided by Honeywell in a letter dated April 27, 2018. No remediation activities have occurred at the Site since our last notice. Site information is provided below.

Honeywell completed remediation of chromium-impacted soil at the Ciasulli Property during 2010. The remedial actions, approved by the New Jersey Department of Environmental Protection (NJDEP), included in situ treatment in one part of the Site and limited excavation in another area.

Information on the property is provided below. Honeywell has also implemented remedial actions at the former Morris Canal. These actions are described in notice letters pertaining to the Morris Canal and New Jersey City University.

The Ciasulli Property

The Ciasulli Property, operating as Metro Honda, is an automobile dealership that encompasses approximately 3 acres along Route 440 between Carbon Place and Fisk Street in Jersey City, New Jersey (see attached aerial location map). The property consists of two parcels: the main car dealership facility and a separate vehicle parking lot, located east of the main facility. Various utility lines are located on the Site. A remedial investigation showed that soils present on portions of the Site contained hexavalent chromium above New Jersey's most stringent residential soil guideline of 20 milligrams/kilogram.

April 26, 2019 Bob Hass, PSE&G Transmission Utilities on Study Area 5 Site 079 - Ciasulli Property Page 2 of 2

dealership building and Route 440. That area is covered with asphalt paving that prevents exposure to contaminants which may remain in soils.

The owner of the Ciasulli property has placed a deed restriction on the Site that requires Honeywell to maintain these remedial measures. Honeywell is committed to maintaining the integrity of the asphalt cap in compliance with New Jersey law and its obligations under the Ciasulli Consent Decree. Honeywell submitted a Remedial Action Report to the NJDEP during September 2011, which was approved by the NJDEP in February 2012. The NJDEP issued a Restricted Use No Further Action Letter and Remedial Action Permit for soils in May 2012. In 2014, post-remediation sampling was performed and results were included in a Post-Treatment Sampling Results Report submitted in February 2015 and approved by the NJDEP in December 2015. Based on the remedial actions completed and post-treatment sampling results, no further post-remediation soil or groundwater sampling is anticipated and post-remediation cap inspections and reporting will continue under the existing Deed Notice, Remedial Action Soil Permit, and Long-Term Monitoring Plan.

If you are planning to conduct any work on or near the subject property (as shown on attached map), we request that you notify Honeywell at least 10 business days in advance or as soon as the work is known. You can report any such pending work by calling 855-727-2658, a special number Honeywell has obtained in order to receive such notifications.

As always, we appreciate your cooperation. If you have any questions or would like additional information, please feel free to call me at 973-455-3302.

Sincerely,

Maria Karuls

Maria Kaouris Remediation Manager

Attachment: Aerial Location Map

MK:jh/sgf

cc: (electronic copy)

Michael Daneker – Arnold & Porter LLP Jeremy Karpatkin – Arnold & Porter LLP

John Morris - Honeywell

Resa Drasin - Woehling and Freeman

Robert Woehling - Woehling and Freeman

Joseph Clifford – Wood Environment & Infrastructure Solutions, Inc.



April 26, 2019

Comcast Cablevision 2121 Kennedy Boulevard Jersey City, NJ 07305

Subject: Annual Update Regarding Utilities on the Ciasulli Property

540 Route 440, Jersey City, New Jersey

To Whom It May Concern:

Honeywell is providing this annual notice update regarding site conditions and activities at the Ciasulli Property (Site) as part of its focus on preventing any subsurface work from disturbing the environmental remedies implemented at the site, and in accordance with Paragraph 81 of the Consent Decree Regarding Sites 79 and 153 South (Ciasulli Consent Decree).

Under the Ciasulli Consent Decree, Honeywell must provide an annual update notice regarding site conditions and activities related to the utilities in the area of the Ciasulli Property. The previous notices were provided by Honeywell in a letter dated April 27, 2018. No remediation activities have occurred at the Site since our last notice. Site information is provided below.

Honeywell completed remediation of chromium-impacted soil at the Ciasulli Property during 2010. The remedial actions, approved by the New Jersey Department of Environmental Protection (NJDEP), included in situ treatment in one part of the Site and limited excavation in another area.

Information on the property is provided below. Honeywell has also implemented remedial actions at the former Morris Canal. These actions are described in notice letters pertaining to the Morris Canal and New Jersey City University.

The Ciasulli Property

The Ciasulli Property, operating as Metro Honda, is an automobile dealership that encompasses approximately 3 acres along Route 440 between Carbon Place and Fisk Street in Jersey City, New Jersey (see attached aerial location map). The property consists of two parcels: the main car dealership facility and a separate vehicle parking lot, located east of the main facility. Various utility lines are located on the Site. A remedial investigation showed that soils present on portions of the Site contained hexavalent chromium above New Jersey's most stringent residential soil guideline of 20 milligrams/kilogram.

April 26, 2019 Comcast Cablevision Utilities on Study Area 5 Site 079 - Ciasulli Property Page 2 of 2

dealership building and Route 440. That area is covered with asphalt paving that prevents exposure to contaminants which may remain in soils.

The owner of the Ciasulli property has placed a deed restriction on the Site that requires Honeywell to maintain these remedial measures. Honeywell is committed to maintaining the integrity of the asphalt cap in compliance with New Jersey law and its obligations under the Ciasulli Consent Decree. Honeywell submitted a Remedial Action Report to the NJDEP during September 2011, which was approved by the NJDEP in February 2012. The NJDEP issued a Restricted Use No Further Action Letter and Remedial Action Permit for soils in May 2012. In 2014, post-remediation sampling was performed and results were included in a Post-Treatment Sampling Results Report submitted in February 2015 and approved by the NJDEP in December 2015. Based on the remedial actions completed and post-treatment sampling results, no further post-remediation soil or groundwater sampling is anticipated and post-remediation cap inspections and reporting will continue under the existing Deed Notice, Remedial Action Soil Permit, and Long-Term Monitoring Plan.

If you are planning to conduct any work on or near the subject property (as shown on attached map), we request that you notify Honeywell at least 10 business days in advance or as soon as the work is known. You can report any such pending work by calling 855-727-2658, a special number Honeywell has obtained in order to receive such notifications.

As always, we appreciate your cooperation. If you have any questions or would like additional information, please feel free to call me at 973-455-3302.

Sincerely,

Maria Karris

Maria Kaouris
Remediation Manager

Attachment: Aerial Location Map

MK:jh/sgf

cc: (electronic copy)

Michael Daneker – Arnold & Porter LLP Jeremy Karpatkin – Arnold & Porter LLP

John Morris - Honeywell

Resa Drasin - Woehling and Freeman

Robert Woehling - Woehling and Freeman

Joseph Clifford – Wood Environment & Infrastructure Solutions, Inc.



April 26, 2019

John Hroncich Operations Manager SUEZ North America (formerly United Water Company) P.O. Box 103 Lake Hiawatha, NJ 07034

Subject: Annual Update Regarding Utilities on the Ciasulli Property

540 Route 440, Jersey City, New Jersey

Dear Mr. Hroncich:

Honeywell is providing this annual notice update regarding site conditions and activities at the Ciasulli Property (Site) as part of its focus on preventing any subsurface work from disturbing the environmental remedies implemented at the site, and in accordance with Paragraph 81 of the Consent Decree Regarding Sites 79 and 153 South (Ciasulli Consent Decree).

Under the Ciasulli Consent Decree, Honeywell must provide an annual update notice regarding site conditions and activities related to the utilities in the area of the Ciasulli Property. The previous notices were provided by Honeywell in a letter dated April 27, 2018. No remediation activities have occurred at the Site since our last notice. Site information is provided below.

Honeywell completed remediation of chromium-impacted soil at the Ciasulli Property during 2010. The remedial actions, approved by the New Jersey Department of Environmental Protection (NJDEP), included in situ treatment in one part of the Site and limited excavation in another area.

Information on the property is provided below. Honeywell has also implemented remedial actions at the former Morris Canal. These actions are described in notice letters pertaining to the Morris Canal and New Jersey City University.

The Ciasulli Property

The Ciasulli Property, operating as Metro Honda, is an automobile dealership that encompasses approximately 3 acres along Route 440 between Carbon Place and Fisk Street in Jersey City, New Jersey (see attached aerial location map). The property consists of two parcels: the main car dealership facility and a separate vehicle parking lot, located east of the main facility. Various utility lines are located on the Site. A remedial investigation showed that soils present on portions of the Site contained hexavalent chromium above New Jersey's most stringent residential soil guideline of 20 milligrams/kilogram.

April 26, 2019 John Hroncich, SUEZ North America Utilities on Study Area 5 Site 079 - Ciasulli Property Page 2 of 2

dealership building and Route 440. That area is covered with asphalt paving that prevents exposure to contaminants which may remain in soils.

The owner of the Ciasulli property has placed a deed restriction on the Site that requires Honeywell to maintain these remedial measures. Honeywell is committed to maintaining the integrity of the asphalt cap in compliance with New Jersey law and its obligations under the Ciasulli Consent Decree. Honeywell submitted a Remedial Action Report to the NJDEP during September 2011, which was approved by the NJDEP in February 2012. The NJDEP issued a Restricted Use No Further Action Letter and Remedial Action Permit for soils in May 2012. In 2014, post-remediation sampling was performed and results were included in a Post-Treatment Sampling Results Report submitted in February 2015 and approved by the NJDEP in December 2015. Based on the remedial actions completed and post-treatment sampling results, no further post-remediation soil or groundwater sampling is anticipated and post-remediation cap inspections and reporting will continue under the existing Deed Notice, Remedial Action Soil Permit, and Long-Term Monitoring Plan.

If you are planning to conduct any work on or near the subject property (as shown on attached map), we request that you notify Honeywell at least 10 business days in advance or as soon as the work is known. You can report any such pending work by calling 855-727-2658, a special number Honeywell has obtained in order to receive such notifications.

As always, we appreciate your cooperation. If you have any questions or would like additional information, please feel free to call me at 973-455-3302.

Sincerely,

Maria Karris

Maria Kaouris
Remediation Manager

Attachment: Aerial Location Map

MK:jh/sgf

cc: (electronic copy)

Michael Daneker – Arnold & Porter LLP Jeremy Karpatkin – Arnold & Porter LLP

John Morris - Honeywell

Resa Drasin - Woehling and Freeman

Robert Woehling - Woehling and Freeman

Joseph Clifford – Wood Environment & Infrastructure Solutions, Inc.



April 26, 2019

Verizon 540 Broad Street Newark, NJ 07120

Subject: Annual Update Regarding Utilities on the Ciasulli Property

540 Route 440, Jersey City, New Jersey

To Whom It May Concern:

Honeywell is providing this annual notice update regarding site conditions and activities at the Ciasulli Property (Site) as part of its focus on preventing any subsurface work from disturbing the environmental remedies implemented at the site, and in accordance with Paragraph 81 of the Consent Decree Regarding Sites 79 and 153 South (Ciasulli Consent Decree).

Under the Ciasulli Consent Decree, Honeywell must provide an annual update notice regarding site conditions and activities related to the utilities in the area of the Ciasulli Property. The previous notices were provided by Honeywell in a letter dated April 27, 2018. No remediation activities have occurred at the Site since our last notice. Site information is provided below.

Honeywell completed remediation of chromium-impacted soil at the Ciasulli Property during 2010. The remedial actions, approved by the New Jersey Department of Environmental Protection (NJDEP), included in situ treatment in one part of the Site and limited excavation in another area.

Information on the property is provided below. Honeywell has also implemented remedial actions at the former Morris Canal. These actions are described in notice letters pertaining to the Morris Canal and New Jersey City University.

The Ciasulli Property

The Ciasulli Property, operating as Metro Honda, is an automobile dealership that encompasses approximately 3 acres along Route 440 between Carbon Place and Fisk Street in Jersey City, New Jersey (see attached aerial location map). The property consists of two parcels: the main car dealership facility and a separate vehicle parking lot, located east of the main facility. Various utility lines are located on the Site. A remedial investigation showed that soils present on portions of the Site contained hexavalent chromium above New Jersey's most stringent residential soil guideline of 20 milligrams/kilogram.

April 26, 2019 Verizon Utilities on Study Area 5 Site 079 - Ciasulli Property Page 2 of 2

dealership building and Route 440. That area is covered with asphalt paving that prevents exposure to contaminants which may remain in soils.

The owner of the Ciasulli property has placed a deed restriction on the Site that requires Honeywell to maintain these remedial measures. Honeywell is committed to maintaining the integrity of the asphalt cap in compliance with New Jersey law and its obligations under the Ciasulli Consent Decree. Honeywell submitted a Remedial Action Report to the NJDEP during September 2011, which was approved by the NJDEP in February 2012. The NJDEP issued a Restricted Use No Further Action Letter and Remedial Action Permit for soils in May 2012. In 2014, post-remediation sampling was performed and results were included in a Post-Treatment Sampling Results Report submitted in February 2015 and approved by the NJDEP in December 2015. Based on the remedial actions completed and post-treatment sampling results, no further post-remediation soil or groundwater sampling is anticipated and post-remediation cap inspections and reporting will continue under the existing Deed Notice, Remedial Action Soil Permit, and Long-Term Monitoring Plan.

If you are planning to conduct any work on or near the subject property (as shown on attached map), we request that you notify Honeywell at least 10 business days in advance or as soon as the work is known. You can report any such pending work by calling 855-727-2658, a special number Honeywell has obtained in order to receive such notifications.

As always, we appreciate your cooperation. If you have any questions or would like additional information, please feel free to call me at 973-455-3302.

Sincerely,

Maria Karris

Maria Kaouris Remediation Manager

Attachment: Aerial Location Map

MK:jh/sgf

cc: (electronic copy)

Michael Daneker – Arnold & Porter LLP Jeremy Karpatkin – Arnold & Porter LLP

John Morris – Honeywell

Resa Drasin - Woehling and Freeman

Robert Woehling - Woehling and Freeman

Joseph Clifford – Wood Environment & Infrastructure Solutions, Inc.

